-													
Work Ord  May 6, 2010 8.		407											Page 1
Item ID: Revision ID: Item Name:	D4034-5			Accept	Accept Setu					Setup	Start Stop	110011101	
Start Date: Required Date Reference:	uired Date: 13/05/2010 Req'd Qty: 3.00			Cust Item ID: Customer:							!		
Approvals:	Process Pla	n:	Date://0-5-09	Tooling SPC (Y		· · · · · · · · · · · · · · · · · · ·	Date:			Run	Start Stop		
Sequence ID/ Work Center I	D	Operation Description		Set U Run	Jp/ Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr											F
D4034	A			0.00	<del></del>							-	
Large Fab				0.00					(3)	)			
Large Fab			e as per dwg D4034 ole as per dwg using DT9561	0.00	SA	0 05-/3							
		QC5- Inspect part comp	pleteness to step on W/O	0.00		0/05/14				1			
QC Quality Control		Memo		0.00	<u> </u>	3/03/14			-(42	(د			
120		Identify as per dwg & S	Stock Location:	0.00	S	AO.							
Packaging Packaging		Memo		0.00	l	HD (6-05-14	T.	, • (	(3)				<b>,</b>

. خ**فر** 

.

Dart Ae	rospace	e Ltd								
W/O:				WC	RK ORDER CHANG	ES				
DATE	STEP		PF	NGE	Ву	Date C	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
Part No:		PAR #:	Fault Cate	jory:	_ NCR: Yes	No DQA: _	Date:			
	Resolution					QA: N/C Closed: Date:				
NCR:				WORK ORDE	ER NON-CONFORMA	ANCE (NCF	R)			
DATE	CTED	TEP D	escription of NC	Corrective Action Section B			Verificati	On Approval	Ammenta	
DATE	SIEP		Section A	Séction A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	k Section C		Approva QC Inspect
			i							
	·		Ì							

## Work Order ID 58407

May 6, 2010 8:09:57 AM



Page 2

Item ID:

D4034-5

Accept



Setup Start

Stop



**Revision ID:** 

Item Name: Rib

**Required Date:** 13/05/2010

06/05/2010

Start Qty: 3.00 Req'd Qty: 3.00

**Cust Item ID: Customer:** 

Reference:

**Start Date:** 

Anı	prova	ale.
App	DLOAS	415:

Process Plan:

Date:

Tooling:

Date:

Run Start



Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ **Work Center ID** 

130

Operation Description

QC21- Final Inspection - Work Order Release

Set Up/ Run Hours

Number

Draw

Draw Rev.

Plan

Accept Code Qty

Reject Reject Qty Number

Insp. Stamp

Quality Control

Memo

0.00

0.00

Dart Ae	rospace Ltd							·				
W/O:			WO	RK ORDER CHANGES	<u> </u>				1			
DATE	STEP	PR	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto			
						:						
-								·····	*			
								•				
Part No	):	PAR #:	PAR #: Fault Category:					Date:				
	Resolution	on:	Disposition	n: (	A: N/C CI	osed:		_ Date: _	•			
NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section E Action Description Chief Eng	Sign &			Approval Chief Eng	Approva QC Inspec			
							·					

## **Picklist Print**

May 6, 2010 8:10:01 AM

Work Order ID: 58407

Parent Item:

Comments:

D4034-5

Parent Item Name:

Rib

IPP RevA: new issue DD 09.11.23 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 06/05/2010

Required Date: 13/05/2010

Start Qty: 3.00

Required Oty: 3.00

Component Item ID/ Item Name M304TS0.750W.049

Replacement Mfg/ Item ID

Purch Purchased Bin Primary Item Location

No

Last Location Route Seq ID 100

Unit of Measure Hand f

Qty on 344.0914

Otv per Kit 1.4375

Date Issued

Status

Page 1

304 SQ Tube .75x.75x.049W

<b>Location</b>	Loc Qty	Loc Code	
MAT	200		
113763	0		
114323	200		
MAT017	144.0914368		
113763	24.25		
114298	119.841437		4.539
			- · · · · · · · · · · · · · · · · · · ·

Qty

Issued

Dart Ae	rospace	Ltd							
W/O:				WO	RK ORDER CHANGE	S			
DATE STEP			PROCEDURE CHANGE				Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
Part No:		1		gory:					
	Re	esolution		Disposition	1:	QA: N/C CI	osed:	Date: _	<del></del>
NCR:		_	,	WORK ORDE	R NON-CONFORMA	NCE (NCR			
DATE	STEP	D	escription of NC		Corrective Action Section		Verification	Approval	al Approva
DAIL	SILP		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspect
					•				
	-	." "							
			·						

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

QTY -043 ITEM DESCRIPTION D4034-041 AFT UPPER RIB ASSY SHOP COPY х D4034-043 FWD UPPER RIB ASSY RETURN TO D4034-1 RIB 2 D4034-3 RIB ENGINEERING 3 D4034-5 RIB UNCONTROLLED COPY D2327-3 SPACER BUSHING SUBJECT TO AMENDMENT D4021-7 HOOP WITHOUT NOTICE D4021-9 BUSHING WORK ORDER NO. 58407 BS10-5-0C С **D4034-041 AFT UPPER RIB ASSY D4034-043 FWD UPPER RIB ASSY** NEW ISSUE A AJS 10.03.04 REV. DESCRIPTION BY DATE DESIGN AJS DART AEROSPACE LTD DRAWN HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. A D4034 MFG. APPR. SHEET 1 OF 4 APPROVED TITLE

UPPER RIB ASSY, BASKET BASE


COPYRIGHT @ 2010 BY DART AEROSPACE LTD

DE APPR.

10.03.04


DATE

Dart Ae	rospace Ltd	d						1					
W/O:		***************************************	WORK ORDER CHANGES										
DATE	STEP	PR	OCEDURE CHAI	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approv QC Inspect						
Part No	):	PAR #:	Fault Cated	gory:	NCR: Yes	No <b>DQA</b> :	Date:						
			: Disposition: QA: N/0										
NCR:				ER NON-CONFORMAN									
DATE	OTED	Description of NC		В	Verification	n Approval	Approx						
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C		Approva QC Inspect					




Dart Ae	rospac	e Ltd											
W/O:			WORK ORDER CHANGES										
DATE STEP			PR	E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector				
Part No:													
	R	Resolutio	<b>d</b> :	Disposition	n:	QA: N	/C Clo	sed:		Date: _			
NCR:				WORK ORDI	ER NON-CONFOR	MANCE (	NCR)	)		· · · · · · · · · · · · · · · · · · ·			
DATE	STEP		Description of NC			Section B	Verifica	ation	Approval	Approval			
	SIEP	Section A	Section A	Initial Chief Eng	Action Descriptio		ign & Date	Sectio		Chief Eng	QC Inspector		
										<del> </del>			
										· · · · · · · · · · · · · · · · · · ·			
NOTE: D	⊥ ate & initi	al all enti	es					<u> </u>					

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart Ae	rospace	e Ltd								••		
W/O:				WC	ORK ORDER	CHANGE	S					
DATE	STEP		PR	OCEDURE CHA	CEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto	
								`.	ь.	ş <i>Y</i> .		
Part No:			PAR #:		NCR: Yes No DQA: Date:							
	R	esolution:			QA: N/C C	osed:		Date: _	<u>-</u>			
NCR:			·	WORK ORDI	ER NON-CO	NFORMAI	NCE (NCF	<b>?</b> )				
DATE	STEP		escription of NC		Corrective Action Section B				tion	Approval	Approva	
DAIL	SIEP	Section A		Initial Chief Eng	Action De		Sign & Date	Section C		Chief Eng	QC Inspecto	
			•									
	<u>.</u>											
NOTE: D	ate & initia	al all enties	· · · · · · · · · · · · · · · · · · ·								L	

H:\fFORMS\Quality Assurance\ap roved QA\NCRWO RevE



**Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval** DATE **STEP PROCEDURE CHANGE** Bv Qty Chief Eng / Prod Mgh Date QC Inspector Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B Description of NC Verification **Approval STEP** DATE Approval Sign & Initial **Action Description** Section A Section C Chief Eng QC Inspector Chief Eng Chief Eng Date

NOTE: Date & initial all ent ies